26

The following is a table showing the number of quarries under the Stone-quarries Act, also the number of persons ordinarily employed thereat, and the annual output and value of crude stone during 1936:-

Provincial District,		Number of Working Quarries under the Act.	Number of Persons ordinarily employed.	Output of Stone.							
	Name and Address of Government Inspector of Stone-quarries.			Stone or Gravel for Macadamizing or Ballast.	Stone for Harbour- works.	Building or Monu- mental Stone.	Limestone for Agriculture.	Limestone for Cement or Mor- tar.	Phosphate for Agriculture,	Miscellaneous,	Value at Quarry.
Auckland	R. H. Schoen, Mines	237	1,076	Tons. 559,321	Tons. 5,000	Tons. 14,159	Tons. 92,296	Tons. 165,675	Tons.	Tons. 33,700	£ 159,958
Truckienu	Dept., Huntly E. J. Scoble, Mines Dept., Waihi (Hauraki Mining District	20	122	78,230		1,460		•••			21,475
Hawke's Bay	only) R. H. Schoen, Mines Dept., Huntly	32	97	42,127			27,006				10,708
Taranaki Wellington	Ditto	$\begin{array}{c} 11 \\ 34 \end{array}$	56 153	13,041 86,362	9,852	4,639	4,148 9,326			13,000	1,856 $33,979$
Nelson Westland Marlborough	G. W. Lowes, Mines Dept., Recfton	21	127	23,722	7,450		7,796	38,298	•••	33,939	15,887
Canterbury Otago Southland	T. McMillan, Mines Dept., Dunedin	38	350	139,067	26,777	2,560	176,483	37,044			98,998
Totals, 1936		393	1,981	941,870	49,079	22,818	317,055	241,017		80,639	342,861
Totals, 1935		358	2,002	985,446	70,357	26,166	288,559	182,944		55,920	289,274

There were twenty-one fewer men employed than during the previous year, but an increase in the value of the stone produced of £53,587.

## QUARRY ACCIDENTS.

The following is a summary of serious accidents during 1936 at quarries under the Stone-quarries Act:-

								f Accidents.	Number of Sufferers.	
	Ca	use.	-	Fatal.	Serious.	Killed.	Seriously injured.			
Haulage							1		1	
Machinery			•••	• •		• •			• •	; .
Explosives				• •		• •	$^2$	1 1	2	1 1
Falls of ground					• •	• •	; ·	1	: .	1
Miscellaneous					• •	• •	1		1	
Tot	als						4	2	4	2

There were no fatalities at any of the South Island quarries during 1936. An account follows of the four fatal accidents which occurred during the year at North Island quarries:-

On 24th August, Thos. C. Oates, employed at a crushing-plant belonging to the Te Kawa Quarry near Te Awamutu, was run over by a railway truck which was being lowered down the line by another workman. The deceased had stepped backward to get out of the way of the advancing truck, but he stumbled and fell in front of it. He suffered fractures of both legs, as well as other extensive injuries, and he died two hours and a half after the accident.

On 1st September George Lipanovich was fatally injured by a fall of loose clay at Amner's Lime Quarry, Napier. The face was only 11 ft. in height, and Lipanovich, who had been feeding the clay on to an elevator, was driven by the fall on to the buckets of the elevator. He suffered severe body injuries, from which he died the same day.

On 15th December a young man, Alex. W. E. Lyle, was killed instantly at the National Timber Co.'s rhyolite quarry at Ngongotaha. From the nature of his injuries it appeared that a premature

explosion had occurred while he was placing the gelignite in the shot-hole.

After having "bulled" a shot-hole 13 ft. deep at the Matatoki Quarry on 21st December, a kerosenetinful of water was poured down the hole and it was left while the workmen had their midday meal. On resuming work Ivan Lendrich and the quarry-manager, P. R. Hinton, placed safety ropes around their waists and, with a supply of explosives, descended to the below which the shot-hole had been drilled. Lendrich was tamping the "Lithyte," which was being handed to him by Hinton, and, when about 12 lb. of it has been placed in the hole, a plug stuck about 4 ft. from the bottom. Lendrich pressed on to it with the wooden tamping-rod when the charge, or a portion of it, exploded. killing Lendrich instantly. At the inquest the evidence given led the Coroner to add to his verdict a rider that the required clearance between the plugs of explosives and the side of the shot-hole should be maintained to the bottom of the shot-hole.