RETURN of DEFECTS found on the Inspection of Boilers and Fittings in the Otago District during the Financial Year ended the 31st March, 1888.

	Descrip	tion.				Dangerous	Ordinary.	Total.
Blow-off cocks							3	3
Bottoms of shells thin						3		3
Corrosion, internal						2	5	7
Corrosion, external							1	1
Fire-box, vertical boiler, thin						1		1
Furnaces (Lancashire), corrode	$_{ m ed}$			•••			4	4
Furnace (Cornish), corroded			• • •				1	1
Furnaces (Lancashire), injured	l expar	nsion					2	2
Gauges, pressure						3		3
Gauges, water- and test-cocks							10	10
Laminated plates, furnace						1		1
Laminated externally over fire				• • •		1		1
Manholes strengthened							$_2$	2
Mud-holes repaired							3	3
Portable, barrel thin						1		1
Scale, accumulation of			•••	•••		2		2
Screwed stays corroded						1 1		1
Safety-valve out of order						1		1
Tube-plate cracked					•••	1		1
Tubes down through corrosion		•••				2		2

RETURN of Notices given to REPAIR BOILERS in the Otago District during the Financial Year ended the 31st March, 1888.

Date of Notice. Description of Boiler.		Description of Boiler.	Nature of Repairs ordered.		
1887.					
79F 8		Longitudinal tubular	Test-cocks to be put on boiler as instructed.		
* .		Longitudinal tubular	Three water-gauges and test-cocks to be fitted on each boiler.		
T 1 40		Cornish tubular	Blow-off cock to be removed and plate patched.		
T 1 00		Steam-digester	Bolts to be fitted through the stays and angle-irons at top.		
	•••	Longitudinal tubular	Laminated plate over fire; piece to be cut out and patch rivetted on about 15in. square.		
Aug. 13	•••	Cornish	Bridge of angle-iron, 3in. x 3in. x 3in., properly fitted and rivetted, to support crown of furnace.		
Aug. 15		Longitudinal tubular (two)			
Aug. 16		PP 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Five tubes to be taken out for examination and replaced.		
. ~ ~ _			Full set of water-gauge mountings and test-cocks to be fitted.		
		Return tubular	New crown to be put in furnace.		
** *	•••	~	len til i Tall a delet at i la		
Nov. 12		Vertical	New pressure-gauge and mudholes repaired at bottom by bolted patches as directed.		
		Semi-portable	New pressure-gauge and spring-balance to be fitted on, and gauge test-cocks all done up.		
Nov. 17 1888.		Vertical	Mudholes to be repaired by bolted patches as directed.		
		Portable	Patch of 4ft. x 2ft. to be fitted on barrel and fixed as directed.		
7.5 10	•••	Steam-digester (two)	Four new stays in each, of 2in. diameter, secured with nuts, with washer outside of 2in. thick and 12in. diameter.		

Return of Notices given to remove Dangerous Parts of Machinery in the Otago District during the Financial Year ended the 31st March, 1888.

Date of Notice. Description of Machinery.		Nature of Machinery to be removed.		
Aug. 10 Aug. 18	Hydraulic lift Hydraulic lift	Chain to be removed and replaced by a new proof-chain. Chain to be removed and replaced by a new proof-chain. Chain to be removed and replaced by a new proof-chain. Top twin-saw to be removed and replaced by a sound saw.		