Working Dredges Visited by Inspector of Mines, Dunedin-continued.

Name and Situation of Dredge.	Owners.	Dredge-master.	Remarks.
nued.	Central Charlton Gold-dredging Com- T.	T. Barnes	Not working; winches sent to Dunedin for repairs; no boat-hooks and only one buoy on board.
Waimumu Extended	Waimumu Extended Gold-dredging	George Pettigrew	Rules complied with, and the machinery well fenced; no rules posted; all in good order; gangway
Waimumu Central	Vaimumu Central Gold dredging Company	George Bichen	No boat-hooks or light-lines on board. The main tail-box is 60 ft. long by 6 ft. wide, and the return tables are 20 ft. by 12 ft., a total spread of 600 square feet. The dredge is working in swampy ground,
Waimumu	Waimumu Gold-dredging Company	F. Brown	and some announcing is experienced in general fire or and " when he and not be not so that in the not be not stern; old man and stern; old man and stern; old man and stern;
Waimumu Queen	Waimumu Queen Gold-dredging Com- pany	James Cumming	Ġ
Mataura. Eureka	闰	W. R. Knightly	Machinery, late Crockston's "Mountaineer"; pontoons new. I condemned smaller boat as being
Chatton. Gold Creek	Gold Creek Gold-dredging Company	W. Robins	shifted to Mataura Island, the claim at Tuturau being considered unpayable. No boat-books or light-lines on board; fence-rail required at pump-drive; otherwise in good order.
Otama (late Enterprise Gully)	Otama (late Enterprise Gully) Otama Gold-dredging Company	D. O'Leary	Only one boat alongside, the other being in use down the river; fence-rail required at the main drive; only 12 in. of freeboard at the bows; the pontoons are on the small side for river-work, and have
			not sufficient buoyancy to comfortably carry the plant and machinery on board.