

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
2	Lancashire	Patch riveted over longitudinal seams.
1	"	Two longitudinal seams covered with joggled patches, and eighty rivets renewed.
1	"	Two new Galloway tubes fitted.
1	Lancashire tubular	A number of rivets renewed in furnaces.
1	"	Circumferential seams parged and caulked.
1	"	Retubed.
1	Locomotive	Five new screwed stays put in firebox.
1	"	New mudhole-door fitted.
1	"	Patch fitted on bottom of firebox.
1	"	Patch fitted on side of firebox.
1	"	Patch fitted on bottom of outside of firebox, and eight new screwed stays fitted.
1	"	Patch in firebox extended.
5	"	Retubed.
1	"	Retubed, and defective patch renewed.
1	"	Retubed, and fifty new screwed stays fitted in firebox; patch fitted on front tube-plate, and several rivets renewed.
1	"	Retubed, and new tube-plate fitted.
1	"	Sixteen screwed stays in firebox renewed.
2	"	Tube-ends in firebox expanded.
1	"	Twelve new screwed stays fitted in firebox.
1	"	Twelve new tubes fitted.
1	"	Two patches fitted in firebox.
1	"	Two sight-holes cut, and tapered plugs fitted.
1	"	Wasted part of front tube-plate sheathed.
2	Manure-dryer	Manhole-doors riveted.
1	"	New bottom fitted.
1	"	One new plate fitted in bottom.
1	Marine	Patch fitted in bottom of combustion-chamber, and two 1½ in. bar-stays fitted through tube-plates.
1	"	Patch fitted over flanging at bottom of furnace.
1	"	Retubed.
1	"	Several rivets in shell removed.
1	Multitubular	Bottom of circumferential seam riveted.
1	"	Brickwork rebuilt, and several defective rivets renewed.
20	"	Brickwork repaired.
1	"	Bulge cut out of bottom of shell, and blow-off pipe fitted.
1	"	Bulge cut out of bottom of shell, and new mud-leg fitted.
1	"	Bulge cut out of bottom of shell, and new plate fitted.
1	"	Bulge cut out of bottom of shell, and patch riveted on.
2	"	Circumferential seams on bottom recaulked.
2	"	Compensating-rings fitted round manhole-openings.
9	"	Compensating-rings fitted round mudhole-openings.
2	"	Compensating-rings fitted round mudhole-opening, and new door fitted.
1	"	Compensating-ring fitted round mudhole-opening, and three new tubes fitted.
1	"	Compensating-ring fitted round mudhole-opening and manhole-door repaired.
2	"	Cracked portion cut out of bottom of shell, and patch riveted on.
1	"	Defective plate cut out of bottom of shell, and new plate fitted.
1	"	Fifteen rivets renewed in shell.
1	"	Five new stay-tubes fitted.
2	"	Flanged compensating-rings fitted to manhole-openings.
1	"	Fourteen new tubes fitted.
1	"	Lamination cut out, and patch fitted.
4	"	Manhole-door spigots renewed.
1	"	Manhole-door spigots riveted.
2	"	Manhole-openings dressed out, and new doors fitted.
2	"	Mudhole-openings dressed out, and new doors fitted.
1	"	Mudhole-opening dressed out, and new spigot fitted to door.
6	"	New manhole-doors fitted.
1	"	New manhole-door fitted, and compensating-ring round opening.
1	"	New manhole-door and new mud-drum fitted.
14	"	New mudhole-doors fitted.
3	"	New mudlegs fitted.