

No. 3.—RETURN OF NOTICES GIVEN TO REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
1	Locomotive	.. Crown stay-nuts renewed.
1	"	.. Fifteen new tubes fitted.
1	"	.. New firebox fitted.
1	"	.. New tube-plate, new barrel, and retubed.
1	"	.. One hundred new tubes fitted.
2	"	.. Patches fitted in firebox under door.
3	"	.. Patches renewed.
3	"	.. Retubed.
4	"	.. Several new nuts fitted to crown-stays.
3	"	.. Several new screwed stays fitted in firebox.
1	"	.. Sixteen new screwed stays fitted in firebox.
1	"	.. Thirty-nine new screwed stays fitted in firebox.
1	"	.. Twelve new screwed stays fitted in firebox, and patch under door.
1	"	.. Twenty-four new nuts fitted to crown-stays.
1	"	.. Twenty-four new screwed stays fitted in firebox.
1	"	.. Twenty tubes renewed.
1	"	.. Two new longitudinal stays fitted, and compensating-ring round mudhole-opening.
1	"	.. Two patches fitted on external firebox, and retubed.
1	"	.. Two patches renewed in firebox.
1	Manure-dryer	.. New bottom fitted to inner shell.
1	"	.. New tube fitted.
1	"	.. Several rivets renewed.
1	Marine	.. Landings on bottom caulked.
2	Multitubular	.. Bottom back end-plate cut out of shell, and new plate fitted.
6	"	.. Brickwork repaired.
1	"	.. Brickwork repaired, and new hanger fitted to boiler.
1	"	.. Bulge cut out of bottom of shell, and patch riveted on.
1	"	.. Circumferential seam riveted.
2	"	.. Compensating-rings fitted round manhole-openings.
11	"	.. Compensating-rings fitted round mudhole-openings.
1	"	.. Compensating-ring fitted round mud-hole opening, and new door fitted.
2	"	.. Compensating-rings round manhole-openings riveted.
1	"	.. Crown plate of steam-dome patched.
1	"	.. Dog and stay fitted to bulge in bottom.
1	"	.. Doubling plate fitted under hanger at back end of boiler.
1	"	.. Eleven rivets in gusset-stays renewed.
1	"	.. End seam riveted.
1	"	.. Fifteen new rivets put in circumferential seam.
1	"	.. Fifteen new tubes and one new longitudinal stay fitted.
1	"	.. Four stays fitted where tube-plate bulged.
1	"	.. Gusset-stay angle-irons renewed.
1	"	.. Large patch fitted on bottom at back end.
4	"	.. Manhole-doors repaired.
2	"	.. Manhole-door spigots riveted.
3	"	.. Mudhole-doors repaired.
1	"	.. New back tube-plate fitted.
4	"	.. New manhole-doors.
4	"	.. New manhole-door, and compensating-ring fitted round opening.
1	"	.. New manhole-door, and compensating-ring riveted.
13	"	.. New mudhole-doors.
2	"	.. New mudhole-doors and compensating-ring fitted.
1	"	.. New mudhole-door and new spigot for manhole-door.
3	"	.. New studs fitted in mud-doors.
1	"	.. One new longitudinal stay fitted.
2	"	.. Opening for manhole dressed out, and new door fitted.
1	"	.. Part of bottom shell renewed.
1	"	.. Patch fitted on boiler-bottom where bulge cut out.
1	"	.. Patch fitted on boiler under hanger-bracket, and new bracket fitted.
2	"	.. Patch fitted on front tube-plate.
2	"	.. Patch fitted over wasted part of longitudinal seam.
1	"	.. Patch on bottom of shell riveted.
2	"	.. Patches renewed.
4	"	.. Retubed.
1	"	.. Retubed and bottom of shell repaired.
2	"	.. Retubed, and compensating-ring fitted to mud-door.