RETURN OF WRECKS AND CASUALTIES TO SHIPPING REPORTED TO THE MARINE DEPARTMENT, ETC.—continued.

17.76	Name of Mascer.	C. Ostenfeld.	J. D. Frew.	H. Spencer.	A. Reed.	E. Cartner.	F. Mackenz <b>ie.</b>	C. McLeod.	C. Croucher.
Finding of Court of Inquiry.		When giving way to incoming vessel in channel "Ihumata" took sheer to starboard and grounded on side channel, owing to flood tide catching vessel on port bow, making her slow to answer helm. but not causing	any apparent damage Through coal heating at forward bulkhead, fire occurred in galley-bunker, but no dam-	age done to snip or cargo Vessel collided with oil-barge which was being towed by tug, resulting in former having how plating slightly dented. but not suffi-	cient to require repairs  It was found necessary to stop starboard engine, as either shaft was fractured or propeller gone; the latter was afterwards	found to be the trouble  The Court held that the vessel strunk an unchartered rock; that the master, officers, and ever took commendable steps to save this and come and account that them we not	In the cargo and ensure they use the way in loss of life; that a proper survey of the Chatham Islands should be made; and made no order as to costs  Owing to strong set to westward, of which master was unaware, and during passing showers and light winds, vessel grounded on extreme end of spit; but vessel came off on	flood tide, and was found not to have sustained any damage When leaving wharf master kept vessel too wide of dashing light, resulting in passing to west of No. 37 red beacon, which master	failed to see, and, continuing, took the bank 300 ft. outside channel, but doing no damage to ship or cargo.  The Court found that vessel struck submerged object in vicinity of Toms Rock, but whether submerged floating log or a rock Court was unable to say, but was of opinion that, in view of favourable weather conditions, the course steered by the master was a proper one, and that no negligence attributable to him or other members of crew
Wind.	Force.	Light	₩	₩	N.N.W. Moderate	2-9	Light	1 to 2	V. Light
2	Direc- tion.	S.W.	E.N.E.	×.	N.N.W.	ż	Variable	N.E.	zi
	eq.	•	3. 137°	, long.	:	atham	:	:	:
Place where	Casualty occurred	Wanganui River	Lat. 21° N., long. 137° 30′ W.	Lat. 40° 24′ N., long. 73° 51′ W.	Hauraki Gulf	Okawa Bay, Chatham Islands	Farewell Spit	Otago Harbour	Cook Strait
Number	Lives lost.	:	:	:	•	•			;
of	Casualty.	Grounded	:	Collision	Starboard propellor lost	Stranded; total loss	Grounded	Grounded	Struck submerged object
Nature of			00 Fire	8,375 Co			Ď	Gr	
	Cargo.	Ballast	General, 10,500 tons	General, 8,3 tons	General, 30 tons	Bunker-coal and fish, 200 tons	; :	General	Wool, 140 bales
Number of	Passen- gers.			•	อีอี	:	:	:	:
	Crew.	23	5 48	80	1 49	212	& ••••	8 29	29
1975 1976.	ig9A anoT		1,425	4,014	. 771	244	588	818	,
į	Kig.	F. and A.	Schooner	Schooner	F. and A.	Schooner	Schooner	Schooner	Cutter
Vessel's Name	Age, and Class.	Ihumata, s.s., 13 years	Hauraki, motor, 3 years	City of Edinburgh, s.s., 26 years	Arahura, s.s., 19 years	Rama, s.s., 29 years	Opua, s.s., 24 years	Flora, s.s., 40 years   Schooner	Admiral, s.s., 41 years
Dafe of	Casualty.	1924. Nov. 11	, 14	15	<b>.</b> 16	. 17	<u>*</u>	. 21	,, 24