## H.-29.

RETURN of DEFECTS found in BOILERS and FITTINGS in the AUCKLAND DISTRICT during the Financial Year ended the 31st March, 1892. Total. Description. Dangerous. Ordinary. 3 1 2 6 3 Fire-boxes out of shape ... ... • • • . . . ••• Fractured plates Blistered plates... Corrosion, internal 1  $\begin{array}{c} ... \\ 2 \\ 5 \end{array}$ . . . • • • ••• • • • ••• ... 1 ••• ••• ... ... ...

Corrosion, internal					. 1	5	6	
Corrosion, external			•••		1	15	16	
Joints sprung in bottom of b	oiler		••••		•••	2	2	
Tubes defective					•••	8	. 8	
Stays defective			•••	• • • • •	•••	7	7	
-				-				
	efects found	in boiler	s	]	3	42	45	
Defective fittings							-	
Safety-valves			•••		•••	5	5	
Feed-valves	•••	•••	•••			2	2	
Stop-valves	•••		• • •		• • •	1	1	
Pressure-gauges	•••				•••	11	11	1
Water-gauges			•••		•••	8	8	
Spring-balances		•••	• • • •		•••	5	5	
Blow-off cocks and pipes		•••			•••	2	<b>2</b>	
Fusible plugs in furnace-cr	rowns	•••			•••	2	$\frac{2}{3}$	
Feed-pipes					•••	3	3	
Omissions								
Boilers without test-cocks	•••	••.	•••		•••	3	3	
Cross to	امد			-	3	84	87	-
Gross to	otal		•••	••••	ð	04	01	_

RETURN of MACHINERY INSPECTED in the AUCKLAND DISTRICT during the Financial Year ended the 31st March, 1892.

Description of Machinery.	Steam.	Water.	Gas.	Description of Machinery.	Steam.	Water.	Gas.
Ammunition factory	1			Gasworks	4		
Air-compressor	1 ī			Glueworks	1		
Assaying	$\overline{1}$			Hauling	7		
Baths	1			Hoisting	<b>29</b>		
Breweries	13			Ironworks and foundries	15		
Boiling-down and bone-mills				Joineries	<b>2</b>		
Butter-box factory	1			Lifts or elevators (2 hand)	4	34	3
Biscuit factories	3			Lime-works	5	•••	
Boot factory	1 ĭ			Mortar-mills	4		
Block- and pump-works				Maize-mill	1		
Brick-works	5			Oil-, soap-, and candle-	-		
Blacksmiths	6			works	2		
Collieries	4			Plumber and copper-smiths	$\overline{2}$		
0				Pumping and winding	$\overline{2}$		
	26			Pumping	$\overline{5}$		
0 00 11	20			Potteries	$\overset{\circ}{2}$		
Clathing factors	1 -		1	Printing	$\overline{3}$		
	1	•••		Quartz-crushing batteries	ő		
C I featuring	1 2	•••		Rope-works	1		
Charles the second seco				TD-1.1	ī	•••	••••
		•••		Sash and door factories	2	••••	
Chemical manure-works	1	•••		01.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	$\frac{2}{6}$		•••
	L L	•••			$\frac{1}{2}$		•••
Dairy factories and cream-	20		1	1 I I I	1	•••	•••
eries			•••		$\hat{1}$	•••	•••
Dredgers	$\begin{vmatrix} 2\\ 2 \end{vmatrix}$				$\frac{1}{6}$		•••
Docks	-			m č.	6	• •	•••
Electric-lighting	1 32			····	1	• • •	•••
Flax-mills		3		Tinplate-works	Т	•••	•,•
Flour-mills	10	1		Threshing- and chaff-	77		
Flock-mill				cutting-machines	7	•••	•••
Freezing-works	7	••••		Threshing-machines (only)	3	•••	•••
Fish-preserving works	3			Tobacco factory	1	•••	•••
Fruit-preserving works	2			Varnish-works	1		•••
Fellmongeries	5		···	Waterworks	3	•••	
Firewood-cutting	44		1	Winding	14		
Fire-engine	1			Wool-dumping	5		•••
Furniture factory	1			Woollen-mill	1	•••	•••

20