

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
1	Portable	... Crack in firebox-chain pinned.
1	"	... Eight new rivets put in tube-plate.
2	"	... Eight new screwed stays fitted in firebox.
1	"	... Eight new screwed stays in firebox, and compensating-rings fitted to manhole and mudhole openings.
3	"	... Eighteen new screwed stays fitted in firebox.
1	"	... Eighty new screwed stays in firebox, and compensating-ring fitted round mudhole-opening.
1	"	... Extra girder fitted on crown of firebox where bulged.
1	"	... Fifty-three new screwed stays fitted in firebox.
1	"	... Five new screwed stays fitted in firebox.
1	"	... Five new screwed stays in firebox, compensating-ring round mudhole-opening, sight-hole cut, and tapered plug fitted.
1	"	... Five new tubes fitted.
1	"	... Foundation-ring repaired, sight-hole cut, and tapered plug fitted.
1	"	... Four new longitudinal stays fitted.
1	"	... Four new rivets in manhole compensating-ring, and forty-three new screwed stays fitted in firebox.
3	"	... Four new screwed stays fitted in firebox.
1	"	... Mudhole door-opening dressed out and new door fitted.
2	"	... New crowns fitted in firebox.
1	"	... New girders fitted on crown of firebox.
1	"	... New girders fitted on crown of firebox, foundation-ring repaired, and sixty-five new screwed stays in firebox.
1	"	... New longitudinal stays fitted.
2	"	... New manhole-doors fitted.
1	"	... New manhole-door, and eighteen new screwed stays fitted in firebox.
10	"	... New mudhole-doors fitted
1	"	... New patch fitted to foundation-ring.
4	"	... New studs fitted in mud-doors.
1	"	... Nine new tubes fitted.
1	"	... One hundred and thirty-seven new screwed stays fitted in firebox.
5	"	... One new longitudinal stay fitted.
5	"	... One new screwed stay in firebox.
1	"	... One new screwed stay in firebox, and new stud in mudhole-door.
2	"	... One new tube fitted.
1	"	... One new tube and one new rivet fitted.
2	"	... Patch fitted on crown of firebox.
2	"	... Patch fitted on crown of boiler at fusible plug-hole.
6	"	... Patches fitted in firebox.
2	"	... Patches fitted on foundation-ring.
1	"	... Patch fitted on front tube-plate, and two new tubes.
1	"	... Patch fitted on shell, and eighteen new screwed stays in firebox.
3	"	... Patches fitted on smokebox tube-plate.
1	"	... Patches on each side of furnace renewed, compensating-rings fitted on mudhole-openings, and twenty new screwed stays fitted in firebox.
4	"	... Patches in firebox renewed.
16	"	... Retubed.
1	"	... Retubed, and new longitudinal stays fitted.
1	"	... Retubed, and new tube-plate fitted.
1	"	... Seven new screwed stays put in firebox.
1	"	... Seventy new screwed stays fitted in firebox.
3	"	... Sight-holes bored, and tapered plugs fitted.
2	"	... Six new rivets put in front tube-plate.
2	"	... Six new screwed stays fitted in firebox.
1	"	... Six new screwed stays fitted in throat-plate.
1	"	... Sixteen new screwed stays in firebox, and one new longitudinal stay fitted.
1	"	... Strengthening stays fitted to crown of furnace.
4	"	... Tapered mudholes in front tube-plate retapped, and new plugs fitted.
1	"	... Ten new tubes fitted.
1	"	... Thirteen new screwed stays in firebox, compensating-ring round mudhole-opening, and patch fitted in firebox.
1	"	... Thirty-four new screwed stays, and new smokebox.
1	"	... Thirty-two new screwed stays fitted in firebox.
1	"	... Three mudhole-openings fitted with compensating-rings.