No. 3.—Return of Notices given to repair Boilers—continued.

Number.	Type.	Description of Repairs.
1	Portable	Two new tubes and patch fitted on back tube-plate.
1	rortable	Two flow tubes and patch flowed on back tube-plate. Two top rows of screwed stays in side sheets renewed, and top row
*	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	in back head.
1	Semi-portable	0 (1 - 1 - 0) 1 - 1 - 1 - 1
1	,,	Compensating-rings fitted round two mudhole-openings and fire
_		door, two new mud-doors fitted, and six new rivets put in shell.
1	,,	Four new screwed stays and patch fitted in firebox.
$rac{1}{1}$,,	,
1	"	Thronty eight now governed story fitted in freher
1	•	M-control form now governed store fitted in finehous
$\bar{1}$,,	m
1	Semi-tubular	D
_		fitted on bottom of shell.
1	,,	
$\frac{1}{1}$,,	Patch 18 in. square riveted on bottom of shell under blow-down and several rivets in circumferential seam renewed.
		Retubed.
i	, , , , , , , , , , , , , , , , , , , ,	Datuhad and now tube plate fitted
1	,,	Washer and stay fitted over crack in tube-plate.
$\bar{6}$	Traction	A number of new screwed stays fitted in firebox.
1	,,	All new screwed stays fitted in firebox, and two new tubes fitted.
6	,,	Compensating-rings fitted round mudhole-openings.
3		
1	,,	Crown of firebox patched, three new girder-stays fitted, and patch fitted on shell of boiler.
1		Fighty one new governed stays fitted in fusher
1	"	Tille
$\bar{3}$,,,	Forty new screwed stays fitted in firebox.
1	,,	Forty-six new screwed stays fitted in firebox.
3	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Longitudinal stays renewed.
$\frac{1}{a}$,,	Manhole-opening dressed out, and new door fitted.
6	,,	
$\frac{1}{6}$	"	One coupling-pin in longitudinal stay renewed. Patches fitted in firebox.
$\frac{0}{2}$	"	Databas fitted on shall of heiler
$\overline{23}$,,	Detubed
1	,,	
1	,,	Retubed, and forty-two new screwed stays fitted in firebox.
]	,	
1 9	···	Retubed, new front tube-plate fitted, and patch fitted on shell of boiler.
		Several new tubes fitted.
i	"	Several patches fitted in firebox, and lower part of external box
	. "	renewed.
1	,,	Several rivets round firedoor renewed.
2	,,	Studs in manhole-doors renewed.
լ 3	•••	Thirty-nine new screwed stays fitted in firebox.
3 1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Thirty-six new screwed stays fitted in firebox. Three new mud-doors and new manhole-door fitted.
1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Twenty new tubes fitted.
î	, ,	Twenty-seven new screwed stays fitted in firebox, patch renewed
		and eight new tubes put in.
l		Twenty-six new screwed stays fitted in firebox.
1	Vertical cross-tube	Bottom portion of firebox renewed.
$\frac{2}{8}$	"	Collars fitted on crown of boiler round uptake.
8	"	Compensating-rings fitted round mudhole-openings. Five new mud-doors fitted, and two stay-nuts on crown of boiler
	"	rejointed.
2	,,	Four new vertical stays fitted.
2	, , , , , , , , , , , , , , , , , , ,	Manhole-doors repaired.
2	"	New mudhole-doors fitted.
1	"	New uptake fitted.
2	"	One new stay fitted.
3	"	Patches fitted on shell of hoiler
5 1	"	Patches fitted on shell of boiler. Patch fitted round bottom of firebox, and collar on crown of boiler
-	"	round uptake.
1	, ,,	Three new vertical stays fitted, and patch on shell of boiler under