

21	Savaii, s.s., 14 years	Schooner	31	4	..	Trawler	Fire; trifling damage	..	Port Ahuriri	..	..	Nothing to show how fire originated	Edward Fredericks.
28	Strathelyde, s.s., 4 years	Schooner	2,842	33	..	Coal	Damaged rudder	..	Lat. 49° 40' S., Long., 158° 48' E.	W.	Gale	Heavy seas caused the rudder-stock to break	W. G. Watt.
29	Rarawa, s.s., 8 years	Schooner	460	..	..	..	Loss of life	1	Between Onehanga and New Plymouth	..	..	A passenger named Joseph Thompson was found to be missing when the vessel arrived at New Plymouth, and is supposed to have fallen overboard	W. F. Norbury.
Oct. 9	Victoria, s.s., 7 years	Schooner	1,869	75	55	General	Stranded; no damage	..	Port Chalmers	..	..	In making room for another steamer she grounded on a sandbank, but got off without injury	G. F. Entwistle.
"	Sterling, s.s., 19 years	Schooner	25	9	..	Nil	Collision; no damage	..	Kaipara Bar	N.	Light	When the tug "Sterling" was approaching the "Eliza Firth" to take her in tow she ran into the stern of the latter vessel	(J. Murray.
"	Eliza Firth, 41 years	Schooner	143	8	..	Produce	Collision; no damage, £100	..		..	..	..	
"	Isabella de Fraine, 9 years	Ketch	93	5	..	Timber	Stranded; no damage	..	Kaipara Bar	N.E.	Fresh breeze	When heaving in anchor the vessel drifted on to a sandbank	A. Running.
Nov. 10	Putiki, s.s., 6 years	Schooner	157	15	..	Cattle	Stranded; no damage	..	In Buller River	S.W.	Light	Helm was starboarded in error, and vessel ran ashore on river-bank, but got off shortly afterwards	F. Dewhuist.
"	Kaitangata, s.s., 3 years	Schooner	1,219	27	..	General	Stranded; no damage	..	Bluff Harbour	S.E.	Light	Vessel was carried by tide on to a sandbank, and stuck for about half an hour	A. M. Edwin.
"	Defender, s.s., 9 years	Ketch	109	12	..	Timber	Stranded; trifling damage	..	Bar, Karamea River	S.W.	Fresh breeze	Vessel stranded on bar through insufficiency of water	J. Jamieson.
Dec. 1	Wootton, s.s., 10 years	Schooner	90	10	..	Timber	Stranded; £150 damage	..	Kaiapoi Bar	S.E.	Light	Vessel struck bar and lost her rudder, but was floated into smooth water without further damage	D. Jefferson.
"	Alexa, 5 years	Barquentine	286	12	..	Timber and coal	Stranded; about £400 damage	..	Bar, Wanganui River	W.	Strong	A big sea rolling in caused the vessel to touch bottom and lose steering-way, and, being out of control, she drifted ashore	James White.
"	Maori, s.s., 3 years	Schooner	1,433	..	..	General	Loss of life	1	Off Godley Head	..	..	A passenger named Lawrence was observed falling into the water, but it is not known how he fell overboard. Everything possible was done to rescue him, but he disappeared immediately	B. M. Aldwell.
"	Pateana, s.s., 26 years	Schooner	550	47	..	General	Collision; about £70 damage	..	Picton Wharf	S.	Light	The "Kairaki" when berthing bumped into the "Pateana," moored at the wharf, and damaged plates and bulwarks of that vessel. Accident caused by a lighter having occupied berth allotted to "Kairaki"	J. T. Crawford.
"	Kairaki, s.s., 1 year	Schooner	181	16	..	Produce	Collision; damage, £15	..		..	..	..	
"	Jessie Niccol, 39 years	Schooner	93	7	..	General	Stranded; total loss	3	3 miles S. of Nuggeta, Macquarie Island	N.	Fresh breeze	The vessel was anchored in the roadstead at Macquarie Island when a change of wind made it necessary to shift her, but she missed stays and drifted ashore. The Court considered that the master acted to the best of his judgment in trying circumstances, but was of opinion that he committed an error of judgment in not remaining at his anchorage until there was sufficient wind to enable him to sail out. The master, the first mate, and the cook were drowned.	J. W. Holmes.