

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs,
3	Vertical cross-tube	Patch fitted round bottom of firebox.
1	"	Plate on bottom of shell renewed, and new cross-tubes fitted.
1	"	Several rivets in shell renewed.
1	"	Six new mudhole-doors fitted, and one opening compensated.
1	"	Six rivets renewed in firebox.
1	"	Three rivets renewed in furnace, and patch fitted in firebox.
1	Vertical field-tube	One new tube fitted.
1	"	Retubed, and patch fitted on crown round uptake.
1	"	Spigot fitted to manhole-door, and opening dressed out to fit.
1	Vertical flue	Compensating-ring fitted to manhole-openings.
1	"	Compensating-ring fitted to manhole-opening, and four new vertical stays fitted.
4	"	Compensating-rings fitted to mudhole-openings.
1	"	Compensating-rings fitted to mudhole-openings, and patch fitted on shell under safety-valve chest.
1	"	Foundation-ring repaired.
1	"	New spigot fitted to manhole-door.
3	"	New uptakes fitted.
1	"	New uptakes fitted, and patch round bottom of shell.
1	"	Patches fitted in firebox.
1	"	Patch fitted on shell under safety-valve mounting.
1	"	Patch fitted on shell under fire-door.
1	Vertical tubular	A number of rivets in shell renewed.
7	"	Compensating-rings fitted round mudhole-openings.
1	"	Crack in tube-plate welded.
1	"	Cracked portion of firebox cut out and patch fitted.
1	"	Eleven new tubes fitted.
1	"	Five new tubes put in.
1	"	Four new vertical stays fitted.
1	"	New firebox, new crown, and new tubes fitted.
1	"	One new vertical stay fitted.
1	"	One new vertical stay fitted and patch on crown.
1	"	Patch fitted on shell.
1	"	Patch fitted round furnace-door.
18	"	Retubed.
1	"	Retubed, and compensating-rings fitted round mudhole-openings.
7	"	Retubed, and new top tube-plates fitted.
1	"	Several new tubes fitted.
1	"	Several new rivets put in firebox.
1	"	Slight crack in tube-plate chain-pinned.
1	"	Thin portion of crown patched, and new vertical stay fitted.
2	Water-tube	Bottom row of tubes renewed.
1	"	Eight tubes renewed.
1	"	Four top rows of tubes renewed.
4	"	Retubed.
1	"	Top row of tubes renewed.
448	Total.	

No. 4.—RETURN of NOTICES given to FENCE OF REPAIR DANGEROUS PARTS of MACHINERY, &c., during the Financial Year ended 31st March, 1911.

Number.	Machinery.	Particulars.
1	Air-compressing	Belting.
1	Asphalt-mixing	Machinery.
1	Bacon-factory	Belting.
1	"	Shafting and pulleys.
1	Bagmaking	End of shaft and belting.
2	Bakery	Belting.
1	"	Moulding-machine shaft.
1	"	Side of driving-pulley.
1	"	Wheels of mixer.