

THIRD SCHEDULE.

CLUBS AS TO WHICH RECOMMENDATIONS ARE MADE AS TO IMPROVEMENTS.

<i>First Column.</i>	<i>Second Column.</i>
Name of Club.	Recommendations.
Northern Wairoa Racing Club ..	Sanitary arrangements are very primitive, and require immediate attention.
Opotiki Jockey Club	Course should be wholly railed on the inside, and adequate sanitary accommodation provided.
Te Aroha Jockey Club ..	Adequate sanitary accommodation to be provided in accordance with assurance given.
Thames Jockey Club	Course requires fencing on outside round river-bank, and sanitary accommodation near horse-stalls requires improving.
Whangarei Racing Club ..	Adequate sanitary accommodation to be provided for both sexes in the outside enclosure.
Dannevirke Racing Club ..	Adequate accommodation to be provided for outside public.
Poverty Bay Hunt Club ..	Kennels and appointments poor, and the Commission was not favourably impressed with the condition of the hounds. Assurances should be obtained that hounds, kennels, and general equipment will receive better attention.
Woodville District Jockey Club	Adequate accommodation to be provided for outside public.
North Taranaki Hunt Club ..	Kennels and appointments need improving, and the pack increased. Assurances should be obtained on these matters.
Opunake Racing Club	Adequate provision to be provided for outside public.
Egmont-Waverley Hunt Club ..	Kennels and appointments require considerable improvement, and the pack increased. Assurances should be obtained on these matters.
Foxton Racing Club	Course requires to be partly fenced on the outside to prevent horses running off course into the trees.
Wanganui Jockey Club	The railing on the inside of this course is too low in places, and should be raised where necessary.
Ashburton County Racing Club	Course requires widening, particularly in the straight. The appointments generally are much below the standard of a four-day club. It should be insisted that the appointments be generally improved.
Canterbury Jockey Club	Course requires banking at the turns, particularly at Cutts's corner and the turn into the straight. This matter requires immediate attention.
North Canterbury and Oxford Jockey Club	Course rough and uneven; requires immediate reploughing and regrading. Outside accommodation should be improved.
Waimate Racing Club	Adequate provision to be provided for outside public, and conveniences for jockeys.
Reefton Jockey Club	The circumference of this course should be lengthened, and course widened as soon as funds permit.
Waikouaiti Racing Club ..	Appointments generally, and in particular sanitary accommodation (septic tank required) to be improved, course widened (to be widened going out of the straight and turning into the straight) and fenced on the outside at those points.