RETURN of Wrecks on which Inquiries have been held, &c.—continued.

				Num	Number of			Vimher		1	Wind.		
Rig. Register Tonnage. Crew. Passengers Cargo.	Register Tomage. Crew, Passengers Cargo.	Crew. Passengers Cargo.	Passengers Cargo.	Nature of Cargo.		<b>売</b> る	Nature of Casualty.	of Lives Lost.	Place where Casualty took place.	Direction	Force.	Finding of the Court of Inquiry.	Name of Master.
"Redeliff," Ketch 22 3 Grain Str 15 years	22 3 Grain	3 Grain	Grain	Grain	<del></del>	Str	Stranded;	Ħ	Allday Bay	N.N.	Whole gale	Master perhaps showed want of judgment in not leaving bay when he could, but he did not expect that the N.E. wind would attain its height before 11 a.m.,	William Hal- ford.
"Aborigine," Brigantine 132 6 6 General Str	132 6 General	6 General	6 General	General		\$ \$ <del>\$</del>	Stranded;	:	Hokitika River	N.E.	Strong gale	as usual, by which time he would have been ready for sea again.  Casualty first caused by N.E. gale and southerly current setting her on South Spit. The final cause being a heavy freel that came down river and rendered	James Levens.
"Ship 1,000 37 270 General St. classed for 12 years, at Liverpool Lloyds	Ship 1,000 37 270 General	37 270 General	270 General	General			Stranded;	:	Struck upon Chasland's Mistake, and subsequently beached in Cat-lin's Bay	N.W.	Fresh breeze	all preparations to heave her off useless Vessel lost through wrongful act and default of Edmund Joseph Johnson, Master, Abram Forshaw, Mate, and Edward Heselton, Second Mate. Master and mate's certificates cancilled, and second	Edmund Joseph John- son.
2 "Flora Macdonald," Cutter 18 3 5 General Cs 12 years fou	Cutter 18 3 5 General	3 General	5 General	General		fou Cg.	Capsized and foundered; total loss	8 (all hands)	Manukau Bar	≽ ⊗	S.W. Heavy squalls	mate a suspended for two years Loss supposed to larve been caused by some damage done to steering gear, which caused her to put back to Manakan, and that in running in over the bar, not being under the command of her helm, she broached to and capsized. No blame seems attributable to master, owners, or	J. L. Kenny.
Coal	1,185 25 Coal	25 Coal	Coal	Coal		Lost mast, top	Lost mizen mast, main- topmast,	:	Lat. 36° 40' South, i Long. 178° 20' West	S.S.W.	Hurricane	Masts cut away to save vessel which had been thrown on her beam ends by heavy sea	F. W. Crispin.
"Dauntiess," Schooner 72 time of collision collision Ballast Collision Challenger," s., (Schooner 26 1 Ballast part	72 time of Ballast edition 1 Ballast 26 1 Ballast	time of Ballast eclision Ballast	Ballast	Ballast		Part	Collision; partial loss	: :	Between Breakwater and Queen Street Wharf,	S.S.E.	Whole gale	Collision caused through fault of both vessels	William Millar. W. D. Har-
Schooner 55 5 General	55 5 General	5 General	General	General		Stra	Stranded; partial loss	:	Auckland South Spit, at en- trance to Hoki- tika River	S.W.	Moderate Breeze	Flood having come down the river, silted up the bar to the extent of four feet, which was not discernible from signal	greaves. Gilbert Brown.
"Anazi," Barque 468 15 12 General Strai 9 years, A1 at Liloyds 16 years	468 15 12 General	15 12 General	12 General	General		Strai	Stranded; partial loss	:	The Wade, Auck- land	N.E.	Fresh	station or sugar an area of a facility of caused by mismanagement of master whilst labouring under influence of liquor; first mate, Mr. Wise, and second mate, Mr. Marsack, also blamed. Court considered that it had not power to suspend certificates, as the vessel was not seriously damaged. Natical Assessor concurred in finding of Court relaive to misconduct of officers, but not as to want of power of Court to sus-	W. H. Holman.
5 "Sarah and Mary," Brigantine 154 8 Timber Stra 10 years	Brigantine 154 8 Timber	8 Timber	Timber	Timber		Stra	Stranded;	:	Outer North Spit, entrance to Hoki- tika River	S.W.	Moderate Breeze	Penn cerminates Heavy ses striking tug caused her to lose her headway in breakers on bar, when current set vessel on to North Spit. No blame attributable to master	H. Simpson.