RETURN of Wrecks on which Inquiries have been held under the Enquiry into Wrecks Act, or for which Casualty Returns have been received, between the 1877, and the 30th June, 1878.

							nst am	113, 101	ist suly, iou, and the soun sune, 10/8	ne, 1070			
Date	Name of Yessel;	Rie	ister ogse	Num	Number of	Nature	Nature	Number	Place where		Wind.	, , , , , , , , , , , , , , , , , , ,	
Casualty.	Age and Class when known.		Regi ngoT	Crew.	Passen- gers.	Cargo.	Casualty.	Lives Lost.	Casualty happened.	Direction.	Force.	finding of Court of Inquiry.	Name of Master.
1877. July 8	Sto	Schooner	69	:	:	Bullast)	:					Collision caused by the light on board the	(Peter Doile.
	23 years; Isabelle,	*	129	:	:	Coal	partial loss	:	Wellington Harbour	S.S.E.	Strong breeze	"Isabelle," which resset was at anchor, being obscured as the "Stormbird" ap-	\sim
,, 10	South	*	139	18	÷	Ballast)						pronched Casualty caused by carelessness of those on	(John Barnard. (Francis Holmes.
	34 years; Adah,	Ketch	29	ဇ	-	G_{cneral}	Collision; partial loss	:	hinle to westward of Ponui Passage light	W.S.W.	Light	board the "Adah," and the "Southern Cross" not slowing her engines when	\sim
" 14	Jess	Schooner	92	G	-	Copra	Stranded;	:	Rabi Island, Fiji Group	တ်	Fresh breeze	she lost sight of the "Adah's" light	John Urquhart.
" 14	Mer., S ven:	8	237	10	:	Timber	Stranded;	:	4 of a mile outside	Calm	:	Casualty caused by the wind suddenly falling and the heavy swell rolling in	George Loverock.
,, 17	- చ <u>ో</u>	*	34	ಣ	:	Timber	Stranded;	÷	Hokianga Harbour Cullen Point, Port of	:	:	causing the chain to part Vessel at anchor; during night the tide	Louis Pike.
" 17	Fairlie,	2	177	7	:	N.Z. pro-	Stranded;	:	Havelock On a patch of rocks off Rotaro Islands Wai.	БĘ	Moderate	wang her round on to the shore Casualty occurred through an accident	Gregory Seymour
									heke Passage, Auck-				LOILIS.
Aug. 3	Taranaki, s.s., 12 years		327	22	21	General	Collision;		West of Pigeon Bay			"Quiver" considered to blame for not attempting to get out of the way of the	John Griffiths.
	Quirer,	Ketch	20	61	:	Ballast	of suling ressel	:	Entrance, nearer to Port Levy	E.N.E.	Light breeze	"Turanuki" when she was seen approaching. "Quiver" was not seen by "Taranaki" until collision, and it is	
9	<u>д</u>	Schooner	99	13	:	Stores	Stranded;	-	N.E. extreme end of	Þj	Hurricane	doubtful if she had any light burning Wreck caused by a very heavy gale	
. 7		•	247	20	:	(sealing) Coal	rotal loss		Macquarrie Island In Wellington Har-			causing cables to part during the night Collision caused by the "Luna" not keep-	Bezer. Stephen Bascand
	13 years Herald,	2	53	70	:	Ballast (partial loss	:	bour, about 800 vards from wharf	N.W.	Strong breeze	ing out of the way of the "Herald," in accordance with section 15 of the Regu-	
7		Barque	726	24	30	General	Stranded;	-	Farewell Spit	:	Fresh breeze	lations for Preventing Collisions at Sea. Master adjudged guilty of grave default J.	C Donald McKay. John Sayes Davies
	loyears, Al Dyears,						10181					in not using lead and other means of ascertaining his position when so near	
												the shore and on a strange coast. Mus- ter's certificate suspended for three	
												years. The certificate of John Ernest Going, second mate, was auspended for	
												six months, as he was the officer of the	
												waten at the time of the stranding, and did not use proper precautions to keep	
				_						******		the vessel off the shore. The first mate	
				_								was in as grave an error as one master as to the navigation of the ship; the	
							-					Court, however, did not suspend his certificate as he was not responsible,	
	The Boa	The Board of Trade he		the Par	_ \$0 Police	o noimment	— — — — — — — — — — — — — — — — — — —	- 6				being acting under the master's orders*	

" The Board of Trade have reduced the period of suspension of Captain Davies's sertificate from three years to one year, and have granted him a mate's certificate during the period of suspension.