

No. 4.—RETURN of NOTICES given to REPAIR BOILERS during the Financial Year ended the 31st March, 1896.

No.	Type.	Description of Repairs.
2	Cornish ...	New end-plate and angle-iron.
2	" ...	Sighting-doors to be cut.
3	" ...	Renew rivets around mouth of furnace.
2	" ...	Renew plates in furnace.
1	" ...	Renew brickwork setting.
2	" ...	Cracked plates in furnace to be cut out and renewed.
4	" ...	Strengthening hoops around furnace-flue.
3	" ...	Blisters cut out of furnace-plates.
1	" ...	Dome stayed.
5	" ...	Shell patched at blow-off.
1	" ...	Water-gauge mountings renewed.
4	" ...	Shell-plates renewed.
2	" ...	Landings in shell-plating caulked and riveted.
2	Lancashire	Galloway-tubes repaired.
1	"	Shell, patched bottom.
1	Locomotive	Tubes partially renewed.
1	"	Fire-box, rivets in, partially renewed.
3	"	Fire-box, stays in, partially renewed.
1	"	Fire-box, skirt repaired.
1	"	Fire-box, blisters cut out and patched.
1	"	Fire-box, crown-plate renewed.
3	"	Plugs, holes fitted with sockets and new plugs.
2	Marine ...	Furnace hooped.
7	" ...	Furnace patched.
1	" ...	Furnace renewed.
1	" ...	Combustion-chamber repaired.
1	" ...	Combustion-chamber renewed.
2	" ...	Combustion, crown-stays fitted.
3	" ...	Combustion, screwed stays partially renewed.
1	" ...	Steam-space stays renewed.
2	Multitubular	Shell-plating at the top renewed.
5	"	Shell-plating over fire renewed.
6	"	Shell-plating, old patches renewed in plates over fire, and seams caulked.
2	"	Tubes expanded.
2	"	Tube-plate repaired.
8	"	Tubes renewed.
1	"	Tubes renewed partially.
3	"	Compensating-ring around mud-hole.
5	"	Stays, extra, and old ones renewed.
4	"	Brickwork setting renewed.
1	"	Mud-drain renewed.
1	Portable ...	Fire-box renewed.
3	" ...	Fire-box, crown renewed.
2	" ...	Fire-box, crown repaired.
2	" ...	Fire-box, crown-stays renewed.
18	" ...	Fire-box, sides patched.
2	" ...	Fire-box, tube-plates repaired.
19	" ...	Fire-box, screwed stays renewed.
5	" ...	Tubes renewed.
4	" ...	Tubes renewed partially.
3	" ...	Stays, longitudinal, renewed.
2	" ...	Stripped for examination.
20	" ...	Mud-doors patched.
2	Semiportable	Fire-box repaired.
5	"	Stays, longitudinal, renewed.
2	"	Stays, extra fitted in tube-space.
6	"	Tubes renewed.
2	"	Crank-saddle rejointed.
1	"	Crown-stays renewed.
2	Semitubular	Shell repaired.
2	"	Gusset-stays renewed.
1	"	Longitudinal stay fitted.
1	Traction ...	Fire-box renewed.
1	"	Fire-box tube-plate renewed.
3	"	Fire-box patched.
2	"	Fire-box crown renewed.
2	"	Fire-box stays renewed.
4	"	Tubes renewed.
1	"	Tubes partially renewed.