

No. 5.—RETURN OF ACCIDENTS (not Fatal) in connection with Machinery—*continued.*

Name and Address of Owner.	Description of Machinery.	Name and Age of Person injured.	Date and Nature of Accident.	Cause of Accident, and Remarks.
William Ross and Sons, twine manufacturers, Napier	Carding-machine	Timothy McCarthy; aged 18	27th March, 1905: arm drawn into cord-rolls and crushed	Mishap. McCarthy was attending to carding-machine when his foot slipped. While stretching out his arm to save himself from falling he inadvertently thrust his hand between the rolls of machine. His hand and lower part of arm were crushed before machine could be stopped.
R. Hannah and Co. (Limited), Lambton Quay, Wellington	Seam-finisher ..	L. Williams; aged 15	30th March, 1905: pinched and bruised arm	Carelessness. In reaching over the machine while it was in motion her arm came in contact with two small cog-wheels, with the result that the flesh was pinched and slightly bruised. The girl was entirely to blame for the accident in not stopping the machine which she controls by pressure of the foot.

No. 6.—RETURN of ACCIDENTS which proved Fatal in connection with Machinery during the Financial Year ended the 31st March, 1905.

Name and Address of Owner.	Description of Machinery.	Name and Age of Person injured.	Date and Nature of Accident.	Cause of Accident, and Remarks.
Andersons (Limited), Lyttelton	Rivet-making machine	Norman Henderson; aged about 45	17th May, 1905: crushed	Carelessness. While putting belt on pulley to drive rivet-making machine he was caught in belting, carried round shafting, and killed.
New Zealand Pine Company, Invercargill	Twin circular-saws	Henry Davis; aged 32	21st July, 1904: blow under the ear	Mishap. There was an unnoticed split in one end of log. When cut by saw a piece became detached, and flew off and struck Davis.
National Mortgage and Agency Company (Limited) of New Zealand, Dunedin	Shafting for driving grindstone	James Friar; aged 55	21st July, 1904: dismembered	Mishap. Friar was caught in belt and whirled round shaft. No one saw the accident.
City of Wellington Electric Light and Power Company, Harris Street, Wellington	Electric generator-switch	W. E. Warren; aged 34	1st December, 1904: electrocuted	Carelessness. Warren came in accidental contact with a highly charged electrical circuit while handling a switch. He failed to take the precaution to put on the rubber gloves provided for the purpose by the firm when dealing with any switch alteration.
King Solomon Syndicate, Cullensville	Overshot water-wheel	Charles Peter Nielsen; aged 53 years	24th March, 1905: crushed	Mishap. He was cutting the spare end of the shaft, and, while attending to the cutter, his coat must have caught in the set screw in the collar on shaft. The wheel was revolving at the time.

No. 7.—RETURN of STEAM-WINDING-ENGINE DRIVERS to whom CERTIFICATES of SERVICE have been granted from the 1st April, 1904, to the 31st March, 1905.

Name of Person.	Class of Certificate.	Date of Issue.	No.
		1904.	
Alfred Edward Stephens	Winding, service	July 8 ...	48
William Turner	" "	" 8 ...	49
John Brooking	" "	September 19 ...	50
Cornelius John Dixsan	" "	November 11 ...	51
Albert Edward Fenning	" "	" 11 ...	52
George Henry Garrett	" "	December 30 ...	53
		1905.	
James Henry Heath	" "	January 25 ...	54
James Dunstan	" "	" 25 ...	55
Henry Beckett	" "	February 8 ...	56