

	21	Kahu, 12 years	Schooner	36	3	Firewood	Stranded; trifling damage		Chamberlin Island, Haeraki Gulf	N.	Strong breeze	The master was making for shelter, when the vessel missed stays and her stern struck a rock	A. Berridge.
"	21	Laura, 32 years	B'q'tine	326	11	Coal	Disasted; damage, £100	..	Lat. 36° S., long. 164° 23' E.	W.N.W.	Heavy gale	Topgallantmast carried away in a sudden squall	G. P. Wood.
"	22	Victoria, s.s., 9 years	Schooner	1,870	73	General	Fire; damage to cargo, £250	..	Cook Strait, 15 miles south of Pencarrow	W.	Strong breeze	When entering the Buller River two heavy rollers struck the vessel and disabled the steering-gear, and not answering the helm she struck the south mole	G. F. Entwistle.
"	22	Takapuna, s.s., 28 years	Schooner	472	47	General	Stranded; damage, £300	..	Breakwater, Westport	W.	Fresh breeze	When entering the Buller River two heavy rollers struck the vessel and disabled the steering-gear, and not answering the helm she struck the south mole	C. MacLean.
"	24	Altair, scow, 8 years	Schooner	57	4	Cement	Collision with wharf; damage, £70	..	Orakei Bay, Auckland	S.	Fresh breeze	The vessel was making for Orakei Bay and steering by a light which was supposed to be the wharf light, but proved to be a light on sewerage works, and the night being dark the vessel ran into the wharf	C. L. Olsen.
"	25	Kiatare, 3 years	Ketch	11	2	Drain-pipes	Capsized; trifling damage	..	Off Nelson Wharf, Auckland Harbour	S.S.E.	..	On board at the time	B. Burt.
June and July		Feliciana, s.s., 2 years	Schooner	235	32	Ballast	Damage to machinery, &c.	..	Sundry places between Chile and New Zealand	Various	..	The vessel left Lebu, Chili, for Newcastle, N.S.W., and met with very heavy weather, sustaining considerable damage to machinery, steering-gear, boats, and boat-deck	F. R. Clarke.
July 1		Kaipara, s.s., 8 years	Schooner	5,608	91	General	Struck wharf; slight damage	..	Railway Wharf, Auckland	S.S.E.	Light	Vessel bumped into wharf when berthing owing to strong tidal current, and injured a strengthening stringer and two plates	R. de la Cour Cornwall.
"	5	Haere, 8 years	Schooner	99	4	Ballast	Damage to rigging, £60	..	Off Cape Maria van Diemen	S.S.E.	Moderate	Fore rigging on port side carried away, causing fall of lower and top masts	G. Sorensen.
"	8	Beatrice, s.s., 10 years	Ketch	7	2	Fish	Collision; no damage	..	Iron Pot, Port Ahuriri	W.	Light	Owing to accident to steering-gear of "Beatrice" she ran into the "Phantom" moored at the wharf	W. Bain.
"	8	Phantom, s.s., 20 years	Schooner	18	5	Nil	Collision; trifling damage	..	Waikokopu Harbour, Hawke's Bay	Calm	..	The vessel was moored in Waikokopu Bay, when a heavy swell came in, carried away the mooring lines and caused the anchor to drag, and the vessel went ashore	D. A. Sharp.
"	9	Waikonini, 10 years	Schooner	60	4	Timber	Stranded; trifling damage	..	Waikokopu Harbour, Hawke's Bay	Calm	..	The vessel was moored in Waikokopu Bay, when a heavy swell came in, carried away the mooring lines and caused the anchor to drag, and the vessel went ashore	P. A. Polson.
"	24	Bell Flower, 11 years	Ketch	98	7	Produce	Stranded; total loss	1	Near Horseshoe Bay, Banks Peninsula	S.	Gale	The Court held that the master, not being sure of his position, should have stood out to sea, especially as the casts of the lead indicated that he was out of his course. The master was drowned in the wreck	John Dowell.
"	28	Haurofo, s.s., 29 years	Schooner	1,276	8	General	Collision with wharf; damage, £400	..	Glasgow Wharf, Napier	E.	Light	A heavy swell caused the vessel to strike heavily against the wharf, resulting in considerable damage to vessel and wharf	S. Vint.
"	28	Jane Gifford, 3 years	Ketch	20	3	Ballast	Disasted	..	7 miles south-west of Cape Colville	S.S.E.	Strong	The starboard shrouds gave way, and the mainmast went by the board	E. S. Chatfield.
"	31	Oceano, s.s., 11 years	Schooner	3,050	41	General	Collision; no damage	..	Rangitoto beacon, Auckland Harbour	Calm	..	Collision apparently caused by default of the A.B. on the "Vesper" in not keeping a proper lookout	F. W. Davies.
"	31	Vesper, o.e.v., 9 years	Schooner	20	4	Cattle	Collision; trifling damage	..	3 miles north of Kennedy Bay, Auckland	S.E.	Light	Propeller-shaft broke, and the propeller broke off and was lost	T. W. Edington.
Aug. 9		Orete, o.e.v., 2 years	Schooner	92	8	General	Loss of propeller	..	1 mile west of N. Point, Niue	S.E.	Strong breeze	When beating to get into the anchorage the vessel missed stays, and in wearing round the mainmast carried away	K. Bruick.
"	13	Kereru, 5 years	Ketch	100	8	Ballast	Disasted; damage, £200	..		S.E.	..		C. J. Harris.