

April 15	Wainui, s.s., 36 years	Schooner	410	30	39	..	Wellington Harbour ..	N.W.	Light ..	Owing to bolts carrying away the high-pressure cylinder-cover and piston were broken and bent	T. B. Sewell.
"	20 Aupouri, s.s., 17 years	Schooner	250	23	24	General	Manukau Bar	Calm ..	When crossing the bar vessel shipped heavy sea, which caused considerable damage to deck fittings	B. Burk.
"	9 W a i k o n i n i, 21 years	Schooner	23	4	Whangarei ..	N.E.	Gale ..	Vessel ran into gale and lost two topmasts ..	E. Norton.
"	21 Raranga, s.s., 5 years	Schooner	7,956	83	..	General	Queen Street Wharf, Auckland	Fire was discovered amongst copra cargo in poop-space. Cause unknown	C. M. Andrews.
"	22 John, s.s., 23 years	Schooner	134	13	..	General	Pegasus Bay, N.Z. ..	S.E.	Fresh breeze	High-pressure piston broke. No apparent cause	J. Hawick.
"	25 Tekoa, s.s. ..	Schooner	5,369	79	..	General	Lat. 30° 4' S., long. 152° 1' W.	S.W.	Moderate	On arrival at Auckland it was found that a blade had been broken off propeller	A. B. MacRae.
"	30 Tiare Taporo, aux., 8 years	Schooner	173	16	..	General	Long. 175° 45' E., lat. 35° 20' S.	N.E.	Strong	Vessel sprung a leak and put back to Auckland as pumps could not keep water down	William Ruth.
"	30 Tredenham, s.s., 8 years	Schooner	5,369	55	..	Basic slag	Lat. 26° 1' S., long. 134° 34' W.	W.	Moderate	Blade of propeller was discovered missing. Cause unknown	J. O. Evans.
May 1	Navua, s.s., 16 years	Schooner	1,773	75	86	General	Lat 34° 53', long. 175° 55'	S.E.	Gale ..	Starboard propeller lost in heavy weather ..	A. H. Davey.
"	2 Tasmania, s.s., 9 years	Schooner	4,688	63	..	General	Bluff Harbour ..	N.W.	Light ..	Vessel was coming in against ebb tide and apparently lost steerage-way, the wind causing her to swing ashore	S. F. Martin.
"	2 Alert, 20 years ..	Schooner	98	4	..	General	Ruakaka Beach, Auckland	S.	Light ..	Vessel ran ashore when making port, probably owing to master failing to see that the man at the wheel was attending to his duties	George Mayall.
"	4 Glenelg, s.s., 42 years	Schooner	156	12	..	Coal	Onerahi Wharf, Whangarei	..	Calm ..	The "Glenelg" was lying at wharf when the "Vixen" in berthing was caused to bump into her by the tide	J. E. Quinn.
"	4 Vixen, aux., 42 years	Ketch ..	27	3	The Court found that accident was caused through mate steering for about ten minutes by bright binnacle light and thus temporarily losing sight of coastline; also, that vessel's course was affected by set of current caused by north-east wind	George Wigg.
"	4 Cygnet, s.s., 37 years	Schooner	70	9	1	General	Off Point Gibson ..	N.N.E.	Moderate	The Court found that the master of the "Tiroa" had committed a breach of the Regulations for preventing Collisions at Sea by omitting to indicate by sound-signals that he was about to alter his course to starboard, thus causing collision, and was ordered to pay the Minister's costs	A. J. Murray.
"	13 Tiroa, s.s., 6 years	Schooner	94	10	..	General	Auckland Harbour ..	E.N.E.	Mode-rate	The launch was employed fishing, and was driven on the rocks and totally wrecked	L. D. Clark.
"	13 Peregrine, s.s., 29 years	Ferry-boat	162	4	about 150	Passengers	A sudden change of wind caused the vessel to miss stays and she was driven ashore, the engines not being sufficiently powerful to keep her off	W. L. K. Bishop.
"	20 Italy, s.s. ..	Launch	..	2	Whale Island, Bay of Plenty	..	Leavy
"	26 Lizette, aux., 41 years	Ketch ..	21	3	Walkeke Island, Auckland Harbour	E.S.E.	Gale ..	Master mistook white riding-light of dredge "222" for one of beacon lights and vessel grounded at upper end of channel	John Regan.
"	27 Breeze, s.s., 13 years	Schooner	286	17	..	General	Otago Harbour ..	S.W.	Strong	..	F. W. Venn.