


THE LATE CAPTAIN FERRER-KHLEED IN AN AEROPTANE ACCIDENT. Captain Feeler, of the French Army, was descending after a flight at Bondogne, when his acroptanc fell, and, the driver falling underneath his machine, was proshed to douth.



A NEW DEFINITE FOR ACTIVITION.

A new twin serew bucket hopper dredge, built for the An-Khad Harbour Rared by Messrs. Fleuding and Ferguson, of Fabiley.

A new twin serew bucket hopper dredge, built bracked on September 30.

THE PERILS OF THE AIR.

ARISHUP DISASTER IN FRANCE FOUR AERONALTS KILLED.

Topleat, plots.

Actation chained its victims in worfully quick succession during September. M. Lefebvre was killed on the 7th, Capath Fecher on the 25th the big dirighbe La Republique was dashed to pieces in its flight from La Paisse to Member, and two moneours, were killed on the spat. In General Real remaining the envelope of the alreshy after the accident, all Archal, the plate of the alreshy after the accident, all Archal, the plate of the Republique who was killed in the accident. Gr The big dirighby setting out on the fatal voyage. The crew of four were all killed.