




D.—1.



ROTOHAUTUKU BRIDGE: VIEW SHOWING CONSTRUCTION OF PIERS. (RIVER NORMAL.)



ROTOHAUTUKU BRIDGE.—RIVER IN FLOOD: FALSE WORK WASHED AWAY.



HAIRINI RIVER ROAD-BRIDGE, NEAR TAURANGA.