




THE WHAKATANE BEING TOWED INTO DOVER.




THE WHAKATANE BEACHED AT DOVER.

The tugs are endeavouring to drag the damaged steamer into water deep enough to float her.



THE WOODEN SHEATHING OVER THE RENT IN THE VESSEL'S SIDE.




WHERE THE CURVE STRUCK THE WHAKATANE.

THE WHAKATANE IN COLLISION—FOG DISASTER IN THE ENGLISH CHANNEL.

The Whakatane, a cargo steamer belonging to the New Zealand Shipping Company, left London on July 4, with a miscellaneous cargo and three passengers for New Zealand. A dense fog hung over the Channel, and about a mile off the ill-famed Cape of Dungeness, she was run down by the French steamer "Circe." The Whakatane was towed into Dover badly down at the stern and holed, but later was temporarily repaired with wood sheathing and towed to London.

(An amusing special article with reference to the taking of some of the above photos, will be found on page 13.)

See "News of the Dominion."



TEMPORARY REPAIRS AND DAMAGED PLATES ON THE WHAKATANE.